

भैरवी ईन्जनीरन्ग **BHAIRAVI ENGINEERING**

Vijayawada 25/10/2021

To, Head of the Department, Civil Engineering, AEC (Autonomous), Surampalem, East Godavari Dist., A.P.

Letter No: BE/GUNTUR/51/2021

Sub: - Requesting for Testing of old building at Guntur -Reg.

Name of the work: - Repair and Rehabilitation of 37 years old building and requires strength report, Guntur, A.P.

For above mentioned work need a soil report for following materials.

S.NO	Name of the equipment	Location	Work to be done
1.	Rebound Hammer	Guntur	Rebound hammer test
2.	Ultra sonic pulse velocity	Guntur	UPV test

(Bhairavi Engineering Pvt Ltd)

Kakinada

ADITYA ENGINEERING COLLEGE

Plot No. 31, Sy 145/B. S. S. Colony, VASANTH NAGAR - KUKATPALLY, Telang SUF AMPALEM: C0533 437 GST No. 36CYRPS6383P1Z1 - PAN Card No.: CYRPS6383P - www.bhairavigroup.com